

The Alfa Owner Index: January 1965 through December 1970

By Ed Berners

References are to Volume and Number

Accessories and Proprietary Products

5-speed shift decal 8-4.
"Safety-Solv" 9-1.
Ash tray for Spider 9-11.
Butyl Cellosolve 10-1.
Steering wheels, "Formula I" 10-12, 11-1.
Adjustable steering wheel 11-2.
Fender cover 11-11.
Bumper guards 13-1.
Inertia safety harness 13-4.
8-speed shift decal 13-5.
TIPOFF: ammeter, halogen lights, radio noise suppressor 13-6.
Bumper and grille guards 8-5, 13-1, 13-7.
Mirror 13-12.
Tape player 13-12.

Air Cleaners

American, for Giulietta 12-5.
European style, for dual Webers 12-8, 13-4.
American for Giulia Solex 13-5.

Air Conditioning

Availability in Italy 11-7.
Non-availability in U.S. 12-1, 12-6.
Home-built unit 13-10.

Alternator

Motorola in Giulietta 8-5, 9-11.
GM Delco 13-2.

Annual Meeting Reports

1965 8-4.
1966 9-4.
1967 10-3.
1968 11-5.
1969 12-5.
1970 13-7.
1971 plans 13-9.

Antifreeze

ARI recommended brands 9-1.
Removal 10-1.

Autodelta

Announcement 8-3.
Description 9-4.
1970 team drivers 13-4.

Battery

Winter operation 9-10.
Delco in Giulia 8-8.
Voltage regulator 9-10.
Prevention of corrosion 10-8.
Cleaning 8-11.

Bearings

Engine, Vandervell 8-2.
Engine, American-made 8-4, 12-5.

Body

Side molding 11-9.
Clouding of windows 12-9.

Books and Magazines

History of Alfa Romeo, Hull and Slater 8-5, 9-11, 13-11.
La Vettura Alfa Romeo dal 1910, Fusi 9-3, 9-11.
Glenn's Alfa Manual 10-5.
158/159 Alfetta 10-8.
Type RL 10-8.
P2 Grand Prix 10-8.
Restoration 10-9.
The Alfa Romeo Story 10-11.
The 6C 1750 Alfa Romeo 11-12.
Quattroruote 12-1, 13-3.
Style Auto, Auto Italiana 13-3.

Brake Fluids

Recommended brands 11-11.
Castrol Girling Amber 8-4, 10-7.
ATE Blau "H" 10-7.
Delco Supreme 550 11-7.
Castrol Girling Crimson 11-7.
Castrol LMA 11-7.

Brakes, Disc

Poor braking 10-7.
Vacuum valve maintenance 10-9.
Flushing brake system 11-7.
Brake fluid reservoir recall 12-1, 12-11, 13-1.
Steel brake line, American 12-5.

ATE

Rear brake line modification 10-7.
Rear pads 11-9.
Raybestos racing pads 11-9.
Sticking parking brake 12-4.

Dunlop

Regrinding discs 10-1.
Raybestos racing pads 10-5.
Rust on calipers 11-7.
Sticking parking brake 12-4.
Can be replaced by ATE 12-6.
Servo unit for non-power brakes 12-9, 13-10.

Girling

Regrinding discs 10-1.
Raybestos racing pads 10-5.

Break-In, Procedure 10-12.

Bylaws, AROC 13-7.

Camshaft Cover

Aluminum washers required 10-7.
Gasket fastening with PCV 10-9.
New improved gasket 10-12.
Torque for nuts 10-12.
Gasket for cars without front lugs 11-2.
Goop in the PCV plumbing 12-8.

Camshaft Timing

Dealer bulletin, advanced timing 10-9.
With dial indicator 11-10.
Specs for all models 11-10.
Reference marks 11-10.
Fine adjustment 13-12.

Carburetors, Solex

Specs, jets for performance 8-1.
Exploded view 8-8.
Adjustment of secondary 8-10.
Modification 9-6.
Anti-icing shield 10-7.
Kit, American-made 12-5.

Carburetors, Weber

Installation in 2600 9-2.
Fuel line problems 11-2.
Kit for 1750 12-8.
Smog tests 13-9.
Cold air box, jets, foam cleaners 13-9.

Chapters

Addresses 8-10.
Directors for 1967 10-5.
Oregon (Portland) 11-9.
Roster of active chapters 12-4.
Northwest (Seattle) 12-6.
Liaison, assistance 13-3.
New chapters forming 13-5, 13-11.
Insurance 13-7.
Chicago Quatrefoil Enduro 13-12.

Clutch

Stronger springs 10-7.
Hydraulic Fluid 11-11.
Frozen pedal fix 13-4.
Pilot bearing 11-2.

Competition Assistance

1965 8-2.
1966 9-1, 9-8.
1967 10-4.
1968 11-3, 11-6

Competition Preparation

Tire pressure for gymkhanas 8-2.
Conrera components 8-4.
Reinforced traction bar mount 8-4, 8-6.
Heavier stabilizer bar 8-4, 9-2.
Speed equipment 8-6.
Flywheel, lightweight 8-8.
Cams 8-8.
Head milling 8-8.
Optional gears 8-9.
Gear part numbers 9-1.
1150 cc piston/sleeve kit 8-11.
Performance options catalog 9-4, 12-9.
Giulietta series 101 10-2, 10-3, 10-8.

Cylinder Head

Bolts, timing case 8-7.
Milling 1300/1600/2600 8-8.
Core plug leaks 9-3, 10-1, 10-10.
Shaping intake ports, 1600 10-7, 13-10.
Gasket leaks 11-11.
Tightening head nuts 11-11.
Shankle modifications 12-7, 13-12.
Neutra-Rod 13-10.

Cylinder Liners 7-9, 8-1, 11-9.

Dealer List 13-9.

Differential

Optional gearsets 9-8.
Dipstick 11-2.
Recommended oils 11-11.

Directors, AROC

1965 8-4.
1966 9-4.
1967 10-4.
1968 11-5.
1969 12-6.
1970 13-10.

Drawings from photos 13-5.

Driving Technique

Shift points 11-12.
Double-clutch downshift 12-6.

Emergency Flashers

Alfa parts 9-8.
Installation 9-11, 10-9.
Sears unit 10-7.

Engines

List of type numbers 8-10.
Reducing block height 13-5.
Removing broken head stud 13-5.

Exhaust System

Replacement 8-1.
Resonance 8-6, 13-9.
Allen head bolts 10-1.
Abarth for Super 13-6, 13-12.
Conti for Speciale 13-6.

Factory News

1964 production 8-3.
Alfa-Sud plant 11-6.
Sales and service network 12-1.
1969 production figures 13-6.
Electrocardiogram tests 13-11.

Fan and Fan Belt

Hose clamp interference 8-10.
Fan removed 8-8, 9-11, 13-10.
Over-tightening 9-10.
American-made belt 12-5.
Slippage at high rpm 13-6.

Foreign Clubs

S. Africa 13-8, 13-11.

Fuel Injection

Timing 13-1, 13-5.
General 13-12.

Fuel System

Mechanical pump 8-2.
Fuel gauge failure 8-3.
Electric pumps reviewed 8-7.
Tygon tubing 10-3, 11-2.
Fuel pump rebuild 11-2.
Cause of burned valves 11-2.
Fumes, cure 13-8.
Water in gas tank 13-11.

Fuse Holder and Fuses

Headlight flashers 8-2, 8-3, 8-5, 10-9, 10-12, 13-2.

Improved wiring 8-3.
Loose spring clips 10-7.
Periodic maintenance 11-2.
Corrosion cure 12-12.

Gearbox

Lubrication 8-2, 12-8.
Dentax 8-2, 10-3, 13-7.
Moly 8-2, 13-7, 12-8.
Shift pattern decal 8-4.
Optional gears 8-9, 9-1.
Change in lubricant 9-8.
Conversion to 5-speed 10-10.
Dipstick 11-2, 9-7.
Recommended oil 11-11.

- Shift points 11-12.
- Removal 13-5.
- Detailed advice 13-7.
- General Information**
- Engine type numbers 8-10.
- List of model numbers 8-4, 9-7, 9-11.
- Scattershield 10-5.
- Factory competition engine 11-1, 11-6.
- Competition Advisory Service 12-2, 12-4.
- Driver's School 12-7.
- Shankle shop 12-9, 12-12.
- Modified injection pump 12-9.
- Giulia Super 13-3.
- Complete preparation of 1600 Duetto 13-9.
- Racing pistons 13-10.
- Generator**
- Winter operation 9-10.
- Lucas negative-ground 9-10.
- Bosch, specs 9-10.
- Failure 13-12.
- Heater and Defroster**
- Auxiliary heater 8-1, 8-3.
- Hose lubricant 8-3.
- Fan motor 8-3.
- Heater gurgles 8-4, 11-1.
- Circulation 8-8.
- Gasoline heater 9-3.
- Without fan motor 9-7.
- Winter preparation 9-10, 11-1.
- Blower and ducting 8-9.
- Switching hoses 10-8.
- Water hose bursting 13-4.
- Hints**
- Thawing frozen locks 8-1.
- Silicone lubricant 8-3.
- Cleaning spark plug wells 8-8.
- Removing oil from cooling system 9-1.
- Throttle pivot lubrication 9-3.
- Keeping warm overnight 9-10.
- Never-Seez compound 9-11.
- Pipe-cleaner dipstick 9-7, 11-2.
- Simple emergency flasher 9-11.
- Timing chain replacement 10-1.
- Paint timing marks 10-10.
- Plastic window cleaner 11-7.
- For longer engine life 11-7.
- Changing plugs in cold 12-12.
- Good glue 12-12.
- Removing broken head stud 13-5.
- Anti-fogging 13-12.
- History**
- Discussion 8-5.
- Evolution of 1300 9-11.
- Production and prices, for 1500, 6C1750, 8C2300, 8C2900 9-12.
- Tipo B 2600, 8C35, Bi-Motore, 8C2900-A/B, 8C308, Tipo 158 10-3.
- Resume of 1300/1600 models from 1954 1954-66 10-8.
- Crest and Quadrifoglio 12-10.
- Hose**
- Silicone lubricant 8-3.
- Replacements 8-4, 8-5, 10-1.
- Defroster, American 9-11, 10-1, 12-5.
- Air intake, American 12-5.
- Humor**
- Overhead Trauma 13-8.
- On Cars 13-12.
- Ignition**
- Boots for Distributor 8-1.
- Vacuum advance 8-8.
- Coil leads reversed 8-8, 13-5.
- Key switch equivalent 9-7.
- Winter operation 9-10.
- Timing marks 10-10.
- Coils 10-12.
- Waterproof cover 11-11.
- Spark plug wires 9-11, 12-5, 12-7, 12-12, 13-7.
- Capacitive discharge 12-6, 13-9, 13-12.
- Cold starts 13-2.
- Judson magneto 13-6.
- Replacement switch 13-7.
- Delco coil 13-9.
- NGK and Bosch plugs 13-9.
- Noise suppression 13-9.
- Importing Alfas**
- Note 12-12.
- Full discussion 13-6.
- Case history 13-9.
- Index**
- Volumes 5, 6, 7 (1962-1964) 8-3.
- Instruments**
- Oil gauge hose 8-5.
- Idiot lights 9-11.
- Speedometer 10-7.
- Ammeter 13-6.
- Oil pressure senders 12-1.
- Speedometer check 12-7.
- Key Blanks 10-5.**
- Leaks**
- Timing cover gasket 8-1.
- Exhaust manifold studs 8-1.
- Heater inlet/outlet pipes 8-1.
- Engine mount stud 8-2.
- Rain leaks 8-2.
- Oil dipstick tube 13-6.
- Coolant into crankcase 8-8, 10-1, 12-8.
- Oil into cooling system, 9-1.
- Battery 10-8.
- Valve guides 10-9.
- Core plugs 9-3, 10-1, 10-10.
- Camshaft cover 10-9, 10-12, 11-2.
- Cylinder head gasket 11-11.
- Front crankshaft seal 11-11.
- Lights**
- High and low beams 8-2, 8-3, 8-5, 10-9, 10-12, 13-2.
- High beam indicator 8-3.
- Trunk under-good, courtesy light 8-3.
- Rewiring back-up light 8-3, 8-5.
- Back-up light switch 10-11.
- Panel dimmer 9-3.
- Alfa panel rheostat part number 10-11.
- Driving lamps 11-9, 13-12.
- Locks**
- Thawing frozen locks 8-1.
- Right-side lock 8-3.
- Lubrication**
- Discussion 8-2, 12-8.
- Recommended oils 11-1, 12-4, 11-11.
- Complete table 11-11.
- Low oil pressure 8-2, 8-8.
- Comments on moly 8-2, 8-4, 9-7, 12-8.
- Lubricant for hose ID 8-3.
- Oil pressure gauge hose 8-5.
- Ball joints in 1600 8-8, 9-6.
- Throttle pivot bearings 9-3.
- Anti-seize compound 9-11.
- Anti-freeze in oil 10-1.
- Oil pressure senders 12-1.
- Oil changes 12-12.
- Dentax 10-3.
- EP type 9-8.
- Membership Rosters 8-12, 10-6, 11-8.**
- Model Alfas 11-6, 11-7, 11-12, 12-4, 12-10, 13-12.**
- Noises**
- Fifth gear whine 8-3.
- Rattle in dash 8-3.
- Rear end squeaks 8-3, 12-5.
- Heater gurgles 8-4, 11-1.
- High-speed cornering 8-10.
- Squeaking ball joints 9-6.
- Squealing front discs 9-10.
- Radio ignition noise 9-11, 12-12, 13-6.
- Seatback rattles, GTV 10-11.
- Timing chain, lower 11-2.
- Scraping disc brakes 11-2.
- Center bearing 11-6.
- Rear end 12-1, 12-5.
- Dashboard squeak 12-1.
- Shift noises 13-7.
- Officers, AROC**
- 1965 8-5.
- 1966 9-5.
- 1967 10-4.
- 1968 ---
- 1969 12-6.
- 1970 13-7.
- Oil Filter**
- Replacement cartridges 10-11, 11-9, 12-5.
- Toilet paper filter 12-12.
- Oil Painting**
- From photo 10-11.
- Paint and Painting**
- Ditzler equivalents 8-10.
- Giulietta red 9-11.
- Wheels 11-2.
- Original factory paint 12-7.
- Match for red 13-10.
- Parts**
- Wrecking yard 8-3.
- Giulia fan belt 8-3.
- Sears parts 8-4.
- Speed equipment 8-6.
- Giulia wheel bearings 8-6.
- Thermostats for Standard 8-1, 8-7.
- Chrome-plated rings 8-9.
- Giulietta crankshaft 8-11.
- Hubcap clips 9-3.
- Water valve 9-3.
- Piston rings 9-3.
- Brake parts, Sears 9-3.
- Ignition key switch 9-7.
- Points for Bosch 9-7, 9-8, 9-11.
- Key to Alfa numbers 10-10.
- Parts for 6C2500 10-12.
- Back-up light switch 10-11.
- American-made list 12-5.
- Assistance 12-6.
- El Segundo 12-9.
- Air cleaner element 13-5.
- Giulietta parts catalogs 13-5.
- 1300/1900/1000/ 2600 available AROC of Britain 13-1.
- Sears selection, discounts 13-10.
- Photo Contests**
- 1968 11-5.
- 1969 12-6.
- 1970 13-8.
- Positive Crankcase Ventilation**
- Maintenance 10-8.
- Complete removal 10-9, 10-11.
- Installation for Giulias 9-10.
- Goop in the plumbing 12-8.
- Publications by Alfa Romeo**
- List 9-1.
- Prices 13-2.
- Giulietta parts 13-5.
- Questionnaire**
- Replies 12-9.
- Quotes 12-11.
- Racing News**
- Daytona 1965 8-4, 1970 13-4.
- Sebring 1965 8-4, 1966 9-4, 1970 13-4.
- Marlboro 12-hr 1965 8-8.
- Monterey Grand Prix 1965 8-10.
- Refrigerator Bowl 1966 9-1.
- Trans-Am 1966 9-9, 9-10.
- SCCA champs 1966 10-1.
- Kwech's GTA 1966 9-11.
- Alfa victories 9-9.
- 1967 report 10-11.
- Alfa drivers 1968 11-9.
- ARRC 1969 13-1.
- Argentine Temporada 1970 13-3.
- Laguna Seca 1970 13-6.
- 1600 for Formula B 8-4.
- Knauz' TI Super 8-4, 8-10.
- Alf Francis for F/2 8-7.
- Alfa hydroplane 8-11.
- Ausca Mk. VI 9-3.
- Winkler-Van der Vate GTA 9-4.
- GTA speed record 9-8.
- Kwech photo 10-7.
- GTA wreck 10-8.
- Brabham-Alfa 10-12.
- Autodelta engine for F/2 11-6.
- Turbo-charged GTA 11-9.
- McLaren-Alfa for F/1 13-4.
- Ausca for 1970 1304.
- Trans-Am 1970 13-7, 13-8.
- Alfa wins 1970 Trans-Am 13-9, 13-10.
- Radiator**
- Stop corrosion 8-8, 11-2, 12-6.
- Leakage of oil 9-1.
- Antifreeze recommended by ARI 9-1.

- Winter preparation 9-10.
 - Recall Campaign**
 - Brake Reservoir 12-1, 12-11, 13-1.
 - Road Tests**
 - Data from magazines 12-10.
 - Giulia 1300 TI 13-5.
 - Rust and Corrosion**
 - Ziebart 9-11.
 - Giulietta battery 10-8.
 - Prevent radiator corrosion 8-8, 11-2, 12-6.
 - Dunlop disc brakes 11-7.
 - Under carpets 13-6.
 - Safety Harness 13-4.**
 - Scattershield 10-5.**
 - Shock Absorbers**
 - Koni rebuilding 8-4.
 - Gabriel adjustable 9-11.
 - Test specs, all models 9-12.
 - American-made 12-5.
 - Failure of rear mount 12-12.
 - Show Cars 13-8.**
 - Spark Plugs**
 - Recommended brands 8-8, 12-7, 13-2, 13-9.
 - Surface-gap 9-12.
 - Never-Seez compound 9-11.
 - Platinum tip 11-2.
 - Extended tip 12-1.
 - Cause of miss 12-5.
 - Champion NGY 12-11.
 - American brands 12-5.
 - Special Interest Roster 13-10.**
 - Starter**
 - Winter operation 9-10.
 - Lucas negative-ground 9-10.
 - Suspension, Front**
 - Heavy-duty stabilizer reinforcement 9-2.
 - Ball joint servicing 9-6.
 - Replacing ball joints and bushings 9-11.
 - Lubrication 13-9 (note correction 14-2).
 - Towing 13-11.
 - Suspension, Rear**
 - Traction bar mount 8-4, 8-6.
 - Shock absorber mount 12-12.
 - 1750 rear stabilizer bar 12-1, 12-4, 12-7, and especially 13-5.
 - Throttle Control Linkage**
 - Pivot point lubrication 9-3.
 - Interference with starter 9-10.
 - Pedal prevents full opening 13-6.
 - Timing Chain**
 - Replacement 10-1.
 - Tensioner 10-1.
 - Noisy lower chain 11-2.
 - Tipoff**
 - Wheels and tires 13-3, 13-5.
 - Accessories 13-6.
 - Tires**
 - Pressure, Michelin 8-11.
 - Pressure, Kleber Colombe 10-8.
 - Pirelli discounts 12-6.
 - Glossary of tire terms 11-3.
 - TIPOFF 13-3, 13-5.
 - Discussion of radials 13-5.
 - Pirelli studs 13-12.
 - Tools**
 - Metric sockets 9-7.
 - TDC indicator 10-3.
 - Alfa tools 10-4, 10-10.
 - Metric taps, dies, thread gauges 11-9.
 - Camshaft timing 11-10.
 - Oil drain plug 10-11.
 - Trim**
 - Carpet and upholstery spray 8-2.
 - Right-hand door lock 8-3.
 - Carpets 8-3.
 - Stiffener for soft top 8-3.
 - Padding for soft top 8-3.
 - Carpets at discount 13-6.
 - Troubleshooting**
 - Low oil pressure 8-2, 8-8, 12-1.
 - Pressure senders 12-1.
 - Fuel gauge 8-3.
 - Vacuum advance 8-8.
 - Reversed coil polarity 8-8.
 - Burned exhaust valves: loose carburetor 8-8, clogged fuel filter 11-2, discussion 8-4.
 - Starting problems 8-11, 11-2, 13-5.
 - Dynamo light 9-11, 10-7.
 - Braking servo-assist 10-7, 10-9.
 - Hose clamp, fan belt 8-10.
 - Cuts in radiator hose 8-10.
 - Poor performance with Solex 11-2.
 - Webers synchronization 11-2.
 - Miss during acceleration 12-5.
 - Failure to reach red-line 12-5, 13-6.
 - Hard starting, 1750 13-5.
 - Universal Joints, American**
 - American-made 12-5.
 - Valves**
 - Burning 8-2, 8-4, 8-8, 11-2, 13-11.
 - Sodium cooled 8-4, 8-5.
 - Valve guide oil seals 10-9.
 - Vintage**
 - Parts 1900 8-2.
 - Valves for 1750, 2.3 8-2.
 - Automobile Quarterly, review 8-5.
 - 1750 Gran Sport 8-11.
 - Parts, general 9-3.
 - 8C 2300 9-9.
 - 8C 2900 12-9.
 - 8C 2300 9-12.
 - Rally for pre-1940 Alfas 9-12.
 - Jano 8-cylinder cars 10-3.
 - 6C 1750 restoration 10-9.
 - The Alfa Romeo Story 10-11.
 - Technical inquiry service 10-12.
 - 6C 2500 parts and information 10-12.
 - The 6C 1750, book 11-12.
 - Voltage Regulator**
 - Specs and modification for Bosch 9-10.
 - Replacement 10-7.
 - Warnings, Cautions and No-No's**
 - Overtightening water pump 8-1.
 - Exhaust manifold studs 8-1.
 - Frozen windows 8-1.
 - Engine mount stud 8-2.
 - Lugging engine 8-4.
 - Neglect of tuning 8-4.
 - Head-to-timing case bolt 8-7.
 - Ball joints 8-8.
 - Fan belt-hose clamp interference 8-10.
 - Water hoses 8-10.
 - Generator mounting 9-10.
 - Use of Marelli starter 9-10.
 - Camshaft cover washers 10-7.
 - Sodium exhaust valves 10-3.
 - PCV servicing 10-8.
 - Stabilizer bar mounting bracket 9-2.
 - Cylinder liner length 11-9.
 - Tighten cylinder head 11-11.
 - New pilot bearing 11-2.
 - Fan belt slip 13-6.
 - Replacing synchronizers 13-7.
 - Wheels**
 - Cast magnesium 9-6.
 - Aluminum 10-5.
 - 14 x 5½ J with ATE brakes 11-1.
 - Paint 11-2.
 - TIPOFF 13-3, 13-5.
 - Welded wider 13-8.
 - Windshield Emblems**
 - AROC 13-8.
 - Trans-Am 13-11.
 - Windshield Wipers and Washers**
 - Parking switch thermal cutout 8-1.
 - Wired through ignition 8-3.
 - Anti-scratch treatment 9-7.
 - Park location 10-1.
 - Failure to stop 11-7.
 - Failure to park 10-10, 11-7.
 - Foot switch wiring 11-7.
 - 2-speed or intermittent 11-10.
 - Washer bag 13-6.
 - 2-speed kit 10-12.
 - ANCO for 1750 13-8.
 - Winter Operation**
 - Frozen locks 8-1.
 - Frozen windows 8-1.
 - Thermostat 8-1, 11-1.
 - Auxiliary heater 8-1.
 - Complete run-down 9-10.
 - Coils 10-12.
 - Engine oil 11-1.
 - Heater maintenance 11-1.
 - Starting 8-11, 11-1, 13-2, 9-10.
 - Hard starting 1750s 13-5, 13-7.
-
- Giulietta 1300, General**
 - Use of 1600 rear axle 8-4.
 - Speed equipment 8-6.
 - Replacement crankshaft 8-11.
 - Windshield washer switch 9-7.
 - Coil for winter 9-10.
 - Alternator installation 9-11, 8-5.
 - Evolution of 1300 engine 9-11.
 - Corrosion under battery 10-8.
 - 5-speed gearbox 10-2.
 - Valve guide oil seals 10-9.
 - Sodium exhaust valves 10-2, 10-3, 10-8.
 - Competition preparation parts 10-2, 10-3, 10-8.
 - Cylinder liner length 11-9.
 - Camshaft timing data 11-10.
 - Front crankshaft seal 11-11.
 - Cylinder head torque leaks 11-11.
 - Giulietta 1300 Spider**
 - Treatment for rain leaks 8-2.
 - Top stiffener prevents draft 8-3.
 - Giulia top fits late Giulietta 9-11.
 - Giulietta 1300 Spider Veloce (Super Spider)**
 - Conversion from Marelli to Lucas 9-10.
 - Giulietta 1300 Sprint**
 - Special information offer 8-5.
 - Giulietta 1300 Sprint Veloce**
 - Conversion from Marelli to Lucas 9-10.
 - Why GTVs are faster than GTs 10-11, 13-1.
 - Driving lamps 11-9.
 - Air cleaner from 1750 12-8, 13-4.
 - Higher compression pistons 13-1.
 - Giulia 1600 Sprint GTA**
 - Introduction 8-4.
 - General description 8-11.
 - Technical details 9-1.
 - Land speed record 9-8.
 - Drawings of Autodelta car 10-1.
 - Photo, Trans-Am 10-7.
 - Photo, Trans-Am wreck 10-8.
 - Aluminum wheels 10-5.
 - Giulia 1600 Sprint Speciale**
 - Conti exhaust system 13-6.
 - Giulia 1600 TI**
 - Introduction 8-4.
 - Veloce-conversion 8-8.
 - Rear window defroster 8-8.
 - Ball joint lubrication 8-8.
 - Specs for ignition, fuel pump, and carburetor 8-9.
 - Revised main bearing cap torque 8-9.
 - Points, American-made 9-7.
 - Windshield wiper dimensions 10-1.
 - Rebuilding fuel pump 11-2.
 - Front suspension seizing 11-2.
 - Giulia 1600 TZ**
 - Introduction, Series II 8-6.
 - Photo, Sebring 1965 8-7.
 - Photos 8-8, 13-12.
 - Duetto 1600**
 - Factory hardtop 10-10, 13-6.
 - Amber parking light lens 10-11.
 - Windshield frame 10-11.
 - Bendix electric fuel pump 10-11.
 - GTA exhaust header 10-11.
 - Veloce cams and jets 10-11.
 - Brake fluid reservoir failure 11-7.
 - recall campaign 12-1, 12-11, 13-1.
 - Trunk lid sag 12-5.
 - Shock absorber mount failure 12-12.
 - Servo unit for non-power Dunlop disc brakes 12-9.
 - Driving lights 13-6.
 - Drafts 13-9.
 - Lafayette radio 13-11.